













According to	ISO 2768-m
Measuring DIM=L	Tolerances
0.5 <l<=3.0mm< th=""><th>±0.1mm</th></l<=3.0mm<>	±0.1mm
3.0 <l<=6.0 mm<="" th=""><th>±0.1mm</th></l<=6.0>	±0.1mm
6.0 <l<=30.0 mm<="" th=""><th>±0.2mm</th></l<=30.0>	±0.2mm
30.0 <l<=120.0 mm<="" th=""><th>±0.3mm</th></l<=120.0>	±0.3mm
120.0 <l<=400.0 mm<="" th=""><th>±0.5mm</th></l<=400.0>	±0.5mm
400.0 <l<=1000.0 mm<="" th=""><th>±0.8mm</th></l<=1000.0>	±0.8mm